< Repair Charge Table >

- The repair charges consist of 2-charges as follows: [Standard Charge (including the basic examination)] + [spare parts]
 Even though LINEEYE cannot repeat your problems, you need to pay for the basic examination (12,000 yen).
 Costs in the repair charge table and the actual quotation can be different.
 All shipping charges/ handling charge for bank transfer & custom, VAT are at your own expense.

| • An shipping charges, handning charge for bank transfer a caston, while at your own expense. | | | |
|---|---|----------------------------------|---------|
| Model | Condition | Repair | Fee |
| LE-150P/LE-150L LE-1200 LE-1100/LE-1000 | Cannot monitor RTS line | Change IC | ¥21,000 |
| | Screen has been damaged | Change LCD | ¥35,000 |
| | Cannot turn on the power | Change the power unit, batteries | ¥34,000 |
| LE-2500/LE-3500 LE-2200/LE-3200 LE-2100/LE-3100 | The plastic cover has been damaged | Change the plastic cover | ¥27,000 |
| | Cannot simulate | Change IC | ¥25,000 |
| | Something has been stocked in the connector | Change connector | ¥25,000 |
| | A key gets tore | Change the key sheet *1 | ¥34,000 |
| | LED for RD signal always lights out | Change IC | ¥25,000 |
| | Cannot monitor | Change connector/ cables | ¥31,000 |
| | LEDs light but nothing is displayed in the LCD. | Change the power unit, batteries | ¥42,000 |
| | A specific key does not work | Change ROM | ¥24,000 |
| LE-7200/LE7000 | Cannot turn on the power | Change IC | ¥33,000 |
| | Memory card connector has been damaged | Change connector | ¥35,000 |
| | LED for battery alarm lights very often | Change IC, batteries | ¥41,000 |
| LE-8200A/LE-8200 | Screen has been damaged | Change LCD | ¥79,000 |
| LE-620HS | Cannot measure | Change ICs | ¥70,000 |
| LE-580FX | Connection to the specific PC is unstable | Update firmware | ¥32,000 |
| OP-1B/OP-2B etc OP-SB5F/7FX etc | Specific signals are not displayed | Change IC | ¥15,000 |

*1: The key sheet for LE-2100/LE-3100/LE-1000/LE2000 are not available.